



CNC MARKETİM
www.cncmarketim.com

MODEL NO.	SHAFT DIAMETER	MAIN DIMENSIONS										Mounting dimension				WEIGHT (Kg)		
		H	E	W	L	F	T	K	J	h1	θ	B	N	M×P	S1		S2	
SA16	16	25	20	40	200	17.8	5	11.7	18.5	8	80°	30	25	1×150	5.5	M5	0.200	
SA16					300								75	1×150				0.300
SA16					400								50	2×150				0.400
SA16					500								25	3×150				0.500
SA16					600								75	3×150				0.600
SA20	20	27	22.5	45	200	17.7	5	10	19	8	50°	30	25	1×150	5.5	M6	0.200	
SA20					300								75	1×150				0.300
SA20					400								50	2×150				0.400
SA20					500								25	3×150				0.510
SA20					600								75	3×150				0.610
SA25	25	33	27.5	55	200	21	6	12	21.5	8	50°	35	25	1×150	6.5	M6	0.290	
SA25					300								50	1×200				0.430
SA25					400								100	1×200				0.580
SA25					500								50	2×200				0.730
SA25					600								100	2×200				0.880
SA30	30	37	30	60	200	22.8	7	13	26.5	10.3	50°	40	25	1×150	6.5	M8	0.360	
SA30					300								50	1×200				0.550
SA30					400								100	1×200				0.730
SA30					500								50	2×200				0.920
SA30					600								100	2×200				1.100
SA35	35	43	32.5	65	200	26.5	8	15.5	28	13	50°	45	25	1×150	9	M8	0.460	
SA35					300								50	1×200				0.700
SA35					400								100	1×200				0.950
SA35					500								50	2×200				1.190
SA35					600								100	2×200				1.420